

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

IU1237  
North  
> 1  
1.603 mi.  
8463 ft.

MANHOLE #38173  
WEST 6TH/HIGHLAWN AVE  
BROOKLYN, NY

NY Spills S106969857  
N/A

Site 1 of 2 in cluster IU

Relative:  
Higher

SPILLS:

Actual:  
20 ft.

Name: MANHOLE #38173  
Address: WEST 6TH/HIGHLAWN AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0504677 / 2006-01-09  
Facility ID: 0504677  
Facility Type: ER  
DER Facility ID: 296045  
Site ID: 349611  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
  
SWIS: 2401  
Spill Date: 2005-07-19  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2005-07-19  
CID: 444  
Water Affected: Not reported  
Spill Source: Institutional, Educational, Gov., Other  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-07-20  
Spill Record Last Update: 2006-01-09  
Spiller Name: ERT DESK'  
Spiller Company: MANHOLE #38173  
Spiller Address: WEST 6TH/HIGHLAWN AVE  
Spiller Company: 001  
Contact Name: ERT DESK'  
DEC Memo: "159830. 7/19/2005 12:15 HRS. L. BRADFORD #16463 #9 TROUBLE SHOOTER REPORTS FINDING APPROX 8 OZ OF DIELECTRIC OIL THAT LEAKED FROM A 3W1W JOINT ONTO MUD IN M38173. THIS WAS FOUND WHILE RESPONDING TO A #9 SIDE OFF TICKET ON ACCT# C3503. THERE WAS NO SMOKE, FIRE, OR INJURIES RELATED TO THE SPILL, NOR WERE ANY SEWERS, WATERWAYS, OR PRIVATE PROPERTY AFFECTED. THE SOURCE OF THE SPILL IS THE JOINT ITSELF WHICH HAS BEEN D-FAULTED. THE EXISTENCE OF ANY SEWER CONNECTIONS, SUMPS, OR DRAINS COULD NOT BE VERIFIED AT THIS TIME. ENV STOP TAG# 39092 WAS PLACED AND ONE LIQUID SAMPLE TAKEN ON E PRIORITY FOR PCB ANALYSIS. MR BRADFORD DID NOT HAVE A CHAIN OF CUSTODY FORM AND ONE IS BEING BROUGHT OUT TO HIM, COC INFO TO FOLLOW. J ANDERSON "  
  
Remarks: "LEAKED FROM FEEDER JOINT, IS CONTAINED, NO TO 5 QUESTIONS; PENDING CLEANING AFTER REMOVAL OF FEEDER: CONED # 159830"

All Materials:

Site ID: 349611  
Operable Unit ID: 1107200  
Operable Unit: 01  
Material ID: 2097094  
Material Code: 0541A

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported